

## VARIANCE / FIELD CHANGE NOTICE

V/F No. 60200-SOW-0011-02

PROJECT NO: Task A-21, Rev. 0, 60200-SOW-0011

Page 1 of 1

DOCUMENT NO: 60200-SOW-0011

Date: 12/9/03

DOCUMENT TITLE: SCOPE OF WORK STATEMENT FOR MONITORING WELL PLUGGING AND ABANDONMENT PROJECT, TASK A-21

## VARIANCE / FIELD CHANGE NOTICE (Include justification)

Requirement:

Section V and Variance 1 show a list of wells to be abandoned under Scope of Work Task A-21, Rev. 0, 60200-SOW-0011

Variance:

Add the following wells to the list of wells to be abandoned:

Former Production Area: 2006, 2007, 2935, 2936, 63121, and 63122 will be over drilled to at least five feet below base of glacial till and abandoned per Environmental Monitoring Procedure DRL-01.

OSDF Cell 8 Footprint: 4067, 3067, and 2430 will be over drilled to approximately 50 feet. Borehole will be abandoned with sand to approximately five feet below base of glacial till, followed by 10 feet of bentonite pellets, then the remainder of the borehole filled with K-Grout slurry.

Justification:

Wells in the former production area need to be abandoned due to soil excavation and remediation activities. OSDF Cell 8 footprint wells interfere with construction of the disposal cell.

Requested By: Jonathan Walters

Date: 12/9/03

X IF REQD	V/FCN APPROVAL	DATE	X IF REQD	V/FCN APPROVAL	DATE
X	QUALITY ASSURANCE <i>Michael B. B. / 12-8-03</i>	12-8-03	X	PROJECT MANAGER <i>Jonathan Walters</i>	12/9/03
	DATA QUALITY MANAGEMENT		X	FIELD MANAGER <i>[Signature]</i>	12/9/03
	ANALYTICAL CUSTOMER SUPPORT			OTHER	
	OTHER			OTHER	

REVISION REQUIRED (Document NO. &amp; Title):

[ ] YES [ ] NO

DISTRIBUTION: ECDC